#### REMEDIAL SITE ASSESSMENT DECISION - EPA REGION IV

EPA ID: ALSFN0407161 Site Name: POLLOCK COLLINS OIL

Page 1 of

State ID:

Alias Site Names:		$\omega_{1}$
City: ANNISTON	County or Parish: CALHOUN	State: AL
Refer to Report Dated:	Report Type: PRELIMINARY ASSESSMENT 001	
Report Developed by: STATE		
DECISION:		
1. Further Remedial Site Assessr because:	ment under CERCLA (Superfund) is not required	
X 1a. Site does not qualify for fo (No Further Remedial Action F	urther remedial site assessment under CERCLA Planned - NFRAP)	
1b. Site may qualify for action	n, but is deferred to:	
2. Further Assessment Needed U	nder CERCLA:	
2a. Priority: Higher L		
2b. Other: (recommended ac	tion) NFRAP (No Futher Remedial Action Planned	
DISCUSSION/RATIONALE:		
Contamination not present above levels of concern.		
*		<b>a</b>
(a)		
Site Decision Made by: ANNIE GODFREY		
Signature: (Immi M. De	respect	Date: 09/30/2000

688.99

FROM:

#### ADEM



ALABAMA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT POST OFFICE BOX 301463 \* 1400 COLISEUM BOULEVARD 36110-2059 MONTGOMERY, ALABAMA 36130-1463

PRELIMINARY ASSESSMENT

ON

KING CHURCH FURNITURE (Original Site)
NAPIER FIELD, DALE COUNTY, ALABAMA

EPA ID #:

CERCLA Ref. #: ALSENo407041

ADEM FORM 194 7/99

PRELIMINARY ASSESSMENT

OF

POLLOCK COLLINS OIL

ANNISTON, ALABAMA; CALHOUN, COUNTY

EPA ID NO: 9636330

CERCLIS SITE REF. NO. 7161

Prepared By
Keevin M. Smith
Alabama Department of Environmental Management
Land Division-Hazardous Waste Branch
Site Assessment Unit

#### **TABLE OF CONTENTS**

1. INTRODUCTION	1
2. SITE DESCRIPTION, OPERATIONAL HISTORY, AND WASTE	
CHARACTERISTICS	1
2.1. Location	1
2.2. Site Description	2
2.3. Operational History and Waste Characteristics	2
2.3.1. Operational History	2
2.3.2. Waste Characteristics	2
3. GROUND WATER PATHWAY	2
3.1. Hydrogeologic Setting	2
3.2. Ground Water Targets	2
3.3. Ground Water Conclusions	3
4. SURFACE WATER PATHWAY	3
4.1. Geomorphologic Settting	3
4.2. Surface Water Targets	4
4.3. Surface Water Conclusions	4
5. SOIL ECPOSURE AND AIRPATHWAYS	4
5.1. Physical Conditions	4
5.2. Soil and Air Targets	5
5.3. Soil Exposure and Air Pathway Conclusions	6
6. SUMMARY AND CONCLUSIONS	6
REFERENCES	7
LIST OF ATTACHMENTS	10
LIST OF FIGURES	11

Date:

September 18, 2000

Prepared by:

Keevin M. Smith (Site Investigator)

Site:

Pollock Collins Oil

EPA ID No.:

9636330

CERCLIS No.: 7161

#### 1. INTRODUCTION

Under authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) and a cooperative agreement between the U. S. Environmental Protection Agency and the Alabama Department of Environmental Management (ADEM), a Preliminary Assessment (PA) was conducted at the Pollock Collins Oil Site. The purpose of the investigation was to collect information concerning conditions at the site sufficient to assess the threat posed to human health and the environment and to determine the need for additional investigation under CERCLA/SARA or other action. The scope of the investigation included a review of available file information, a comprehensive target survey, and site reconnaissance of Pollock Collins Oil. Assessment of the Anniston area is ongoing and extensive residential sampling is being conducted at the direction of US EPA as an emergency removal assessment conducted with the support of ADEM. While extensive testing is being conducted, only a small quantity of analytical results was released to ADEM prior to the preparation of this report.

#### 2. SITE DESCRIPTION, SITE HISTORY, AND WASTE CHARACTERISTICS

#### 2.1. Location

The Pollock Collins Oil site is located in Calhoun County, Alabama (Figure 1). To approach the site, take U. S. Hwy 231 North from Montgomery, Al. to Sylacauga, Al. Then take State Hwy 21 North to Anniston, Al. When you reach the City of Anniston stay on State Hwy 21 North, which is known as Quintard Av. Take a left on 10<sup>th</sup> St. and travel approximately seven blocks and then take a left on Glenn Addie Av. You will find the site approximately two blocks on the left. More specifically, the site is approximately a one acre parcel of land located at 605 Glenn Addie Av. in Anniston, Al. The site is in the southeast ¼ of the southeast ¼ of the northeast ¼ of Section 7, Township 16, Range 8 East. The geographic coordinates of the site are 33° 39' 08.93783" N Latitude and 85° 50' 09.76429" Longitude. (Reference 1 and Figure 2)

Calhoun County has a temperate climate with abundant precipitation well distributed throughout all seasons. The climate of Calhoun County is characterized as humid

subtropical with hot summers, and mild winters. The average annual temperature is approximately 62°F with an average annual rainfall of approximately 54 inches. The average temperature in the summer is 80°F and in the winter is 43°F (Reference 5). Runoff in Calhoun County is less than 20 inches per year. (Reference 2)

#### 2.2. Site Description

The Pollock Collins Oil Site consists of five (5) buildings, and four (4) large stilted above ground tanks, used for fuel storage. There are some old fuel pumps, truck and auto batteries, and a few old empty steel drums located on the property. The front of the property, which is the west side of the site, is boarded by Glenn Addie Avenue, and across the avenue is a vacant lot. South of this lot flows an unnamed tributary that feeds into Snow Creek approximately five hundred fifty feet southeast of the site. It runs under Glenn Addie Avenue and borders the site from the South. The site is bordered to the east by municipal property, and to the north by industrial property. A large housing project is located southwest of the site. The area west of the stilted tanks is mostly covered with crushed limestone gravel. The area under the stilted tanks is diked. The majority of the site, apart from the buildings, is covered with grass. A small amount of stained soil and gravel were observed in the March 21, 2000, site visit. The entire site is graded, and generally level (Reference 10).

#### 2.3. Operational History and Waste Characteristics

Pollock Collins Oil Company began operation in 1938. It is a wholesale Amoco Oil Company. Pollock Collins Oil sells diesel, auto fuel, and package lubricants to local fuel stations in the Anniston and surrounding area. John Collins is the current owner and manager of the facility. He has three employees that work at the facility. Mr. Collins sells approximately three million gallons of fuel to about fifteen customers each year. He also indicated that when it rains heavily, and for prolonged periods of time, water from the vacant lot across the street drains across his property. Mr. Collins stated that the unnamed tributary of Snow Creek has overflowed its bank and flooded his property on many occasions (Reference 9).

#### 3. GROUND WATER PATHWAY

#### 3.1. Hydrogeologic Setting

The site is located within the recharge area for the Valley and Ridge aquifer system, and in the outcrop area of the Shady Dolomite. Groundwater in this formation occurs in interconnected solution channels, and potentially large amounts of water can be obtained from these features. Depth to groundwater at the site is expected to be between 0 to 25 feet (Reference 5).

#### 3.2. Ground Water Targets

There are two active public water supply wells located within 4 miles of the site. The

closest active public water supply well is operated by Union Foundry, and is located approximately 1.5 miles to the northwest of the site. The well is 595 feet deep and serves 410 people. The other public water supply well is operated by Lee Brass Company and is located approximately 2.45 miles to the southeast of the site. Most of Anniston receives drinking water from Anniston Water and Sewer Board. The site is not in a designated wellhead protection area, and no wellhead protection areas are located within four miles of the site (Reference 14 and Reference 15).

#### 3.3. Ground Water Conclusions

Of the samples taken at Pollock Collins Oil, none contained heavy metals or PCB's greater than the level of concern established by ATSDR for this site. Analytical data suggests that there is probably no contamination from Pollock Collins Oil leaching into the ground water. Mr. Collins did however indicate that at times the unnamed tributary of Snow Creek has flooded and covered most of his property. This flooding action could leave deposits of contaminants on the said site. The levels of PCBs identified would be consistent with a flooding scenario. Further testing would more fully characterize this deposition.

#### 4. SURFACE WATER PATHWAY

#### 4.1. Geomorphologic Setting

Consolidated sedimentary rocks that range in age from Cambrian to Pennsylvanian underlie the majority of Calhoun County. These rocks have been sharply folded into a series of northeast trending anticlines and synclines complicated by thrust faults. In the extreme southeastern portion of the county metamorphic rocks of the piedmont have been thrust up to the northwest and overlie sedimentary rocks of Cambrian Ordovician age (Reference 5).

The site is located within the outcrop area of the Cambrian age Shady Dolomite (Reference 6 and Figure 3). The Shady Dolomite is approximately 500 feet thick in Calhoun County and consists of a bluish-gray to pale-yellowish-gray thick-bedded siliceous dolomite. This unit is characterized by coarsely crystalline porous chert (Reference 5). Areas underlain by the Shady Dolomite are susceptible to karst formation.

The Jacksonville Fault traverses approximately 1.25 miles to the northwest of the site, and the Cartersville Fault traverses approximately 1.5 miles to the southeast of the site. An unnamed fault traverses approximately 0.25 miles to the southeast of the site. The Jacksonville Fault, Cartersville Fault, and the unnamed fault are thrust faults and generally trend in a northeasterly to southwesterly direction (Reference 6). The structural features in the vicinity of the site should enhance the fractured nature of the bedrock (Figure 3).

The site is situated in southern Calhoun County in what is considered to be the Weisner

Ridges physiographic district if the Alabama valley and Ridge physiographic section. The Weisner Ridges physiographic district consists mainly of Coldwater and Choccolocco Mountains where altitudes are as high as 2,100 feet. Surface water drainage in this district is mainly into tributaries of the Coosa River (Reference 7). The surface elevation at the site is approximately 680 feet MSL(Reference 1).

#### 4.2. Surface Water Targets

Surface water drainage from the site appears to be to the south into a unnamed tributary of Snow Creek. At approximately five hundred fifty feet south east of the site, the unnamed tributary flows into Snow Creek. Snow Creek flows approximately 3.5 miles to the south into Choccolocco Creek. Choccolocco Creek flows to the west and makes-up the remainder of the 15-mile surface water pathway from the site. Snow Creek and Choccolocco Creek are listed with a use classification of fish and wildlife. Choccolocco Creek has a seven day ten year low flow rate of 34 cfs and a seven day two year low flow rate of 53 cfs. Low flow data was not available for Snow Creek (Reference 4). No known surface water intakes for public drinking water supplies are located along the 15-mile surface water pathway from the site. There is no data on the unnamed tributary of Snow Creek (Reference 14).

Along the entire targeted overland drainage and surface water pathways there are no known wetlands that could come in contact with water from the site (Reference 1). The Pollock Collins Oil site, and the land along the banks of Snow and Choccolocco Creek and its intermittent tributaries might be critical to the support of many threatened and endangered terrestrial species (see list of terrestrial species in Section 5.2.). The table below lists the aquatic wildlife that is thought to have a high probability of being exposed to contaminants from the Pollock Collins Site if a substantial amount of contaminants was to enter into the surface water pathway:

Common Name	Listing	Distribution in Alabama			
Blue Shiner	Threatened	Choccolocco Creek			
Southern Pigtoe Mussel	Endangered	Choccolocco Creek			

(Reference 11 and Reference 13)

#### 4.3. Surface Water Conclusion

Analytical data suggests that there are no known levels of contaminants greater than listed on the RCA Tables found on the Pollock Collins Site. A sample collected from within the unnamed tributary drainage course revealed the highest level of PCB's collected in this area. Since this sample was located upstream of the site, it appears contaminants at Pollock Collins are being deposited on site due to flooding events.

#### 5. SOIL ECOPSURE AND AIR PATHWAY

#### 5.1 Physical Conditions

The Soil Conservation Service (SCS) classifies soils at the site as Philo and Stendal fine sandy loams, 0 to 2 percent slopes. The soils in this classification are described by the SCS as areas comprised of one of both of Philp and Stendal soils, which develop from general alluvium on nearly level first bottoms subject to flooding. These soils are moderately well drained and are moderatelyl permeable. The surface soils consist of grayish-brown to dark-brown fine sandy loam, and the subsoils consist of dark-brown to yellowish-brown fine sandy loam to fine sandy clay loam (Reference 3).

#### 5.2. Soil and Air Targets

There are three (3) people working at the site and three (3) people living on properties immediately adjacent to the site. There are twelve (12) houses and two apartment complexes with twelve (12) apartments in each complex within 200 feet of the site. The total number of apartment complexes in the area is thirteen (13). There is a playground and Glenn Addie Community Center located within ¼ mile of the site. The nearest School, Cobb Ave. School, is approximately ¾ of a mile from the site. No daycare facilities were observed seen within ½ of a mile of the site during the site reconnaissance (Reference 10). According to the Alabama 1990 census records, the average number of people living in homes located in the county of Calhoun is 2.59 residents per household (Reference 12). In the following table, the total population within the target area has been broken down into sub-populations that live within each specified distance radius from the site (Attachment 1).

Distance From Site	Population
1/4 mile	211
1/4 to 1/2 mile	756
½ to 1 mile	4268
1 to 2 miles	11905
2 to 3 miles	11382
3 to4 miles	10568
Total Population	39090

#### School Systems and Direction from Pollock Collins Oil Site

Distance Ring	School Name	Direction from Site	Population
0-1/4	None	NA	NA
1/4-1/2	None	NA	NA
1/2-1	Cobb Ave. School	NW	356

	<u></u>	_	
	Johnston Elementary	Е	383
1-2	10 <sup>th</sup> . St. School	Е	178
	Anniston High School	NE	954
	Constantine School	S	234
	Gadsden State Community		
	Coll. Anniston Division	NE	
	Sacred Heat/St. Mary's School	NE	190
2-3	Oxford High School	S	956
	Calhoun Ca. Vocational School	S	28
	Norwood School	N	303
	Wellborn Elementary School	W	750
3-4	Saks Elementary School	N	671
	Saks Middle School	N	412
	Saks High School	N	685

Pollock Collins Oil

Within the 4-mile target area and the 15-mile surface water pathway there are no known wetlands. It is not known if the Pollock Collins Site is a critical habitat for federally designated endangered or threatened species, but the table below lists the terrestrial species that may utilize the land and surface waters located within the specified target areas.

Common Name	Scientific Name	Listing		
Gray Bat	Myotis Grisescens	Endangered		
Red-Cockaded Woodpecker	Picoides borealis	Endangered		
Pygmy Sculpin	Cottus pygmaeus	Threatened		
Blue Shiner	Cyprinella caerulea	Threatened		
Fine-Lined Pocketbook Mussel	Lampsilis altilis	Threatened		
Tulotoma Snail	Tulotoma magnifica	Endangered		
Painted Rocksnail	Leptoxis taeniata	Threatened		
Southern Pigtoe Mussel	Pleurobema georgianum	Endangered		
Mohr's Barbara's Buttons	Marshallia mohrii	Threatened		
Tennessee Yellow-Eyed	Xyris tennessensis	Endangered		

(Reference 11 and Reference 13)

#### 5.3. Soil Exposure and Air Pathway Conclusion

Analytical data suggest that there are no known contaminants greater than that listed on the RCA Tables at the Pollock Collins Site. However sample number PB-009-10 was not taken at the Pollock Collins Site. It was taken on property across the street from the site.

It was 35,000 ppb PCBs. Therefore it is very unlikely for any contamination present at the Pollock Collins Site to have originated at the site. The source would appear to be contamination transported by flooding in the soil and air at the Pollock Collins Site (Attachment 3 and Attachment 6).

#### 6. SUMMARY AND CONCLUSIONS

Analytical data suggests that there are no known contaminants greater than that listed on the RCA Tables at the Pollock Collins Site. Mr. Collins did however indicate that at times the unnamed tributary of Snow Creek has flood and covered most of his property. This flooding action could leave deposits of contaminants on the site. Further evaluation of the site is not recommended as part of the PA/SI Remedial CERCLA process. However, further evaluation as part of the ongoing emergency removal could provide useful information.

#### REFERENCES

- U.S.G.S. 7.5 Minute Series Topographic Quadrangle Maps of Alabama: Anniston 1956 photorevised 1972; Choccolocco 1954 photorevised 1983; Eulation 1956 photorevised 1972; Munford 1956 photorevised 1983; Oxford 1956 photorevised 1983; Hollis Crossroads 1967 photorevised 1983. Scale 1: 24,000.
- 2. Harkins, J.R., 1972, Surface-Water Availability, Calhoun County, Alabama: Map 128: Geological Survey of Alabama.
- 3. Harlin, William V., and Perry, E. A., 1961, Soil Survey of Calhoun County, Alabama; United States Department of Agriculture, Soil Conservation Service.
- 4. Hayes, Eugene C., 1978, 7-Day Low Flows and Flow Duration for Alabama Streams Through 1973, Geological Survey of Alabama, Bulletin 113.
- 5. Moser, Paul H., and DeJarnette, S. S., 1992, Ground-Water Availability in Calhoun County, Alabama: To Accompany Special Map 228: Geological Survey of Alabama.
- Osborne, W.E., Szabo, M. W., Neathery, T.L., and Copelan, C. W. Jr., 1988, Geologic Map of Alabama, Geological Survey of Alabama, Special Map 220 Northwest sheet.
- Planert, Michael, and Pritchett, J. L. Jr., 1989, Geohydrology and Susceptibility of Major aquifers to Surface Contamination in Alabama; Area 4, United States Geological Survey, Water Resources Investigation Report 88-4133.
- 8. Warman, J.C., and Causey, L. V., 1962, Geologic Map of Calhoun County: Map 17 Geological Survey of Alabama.
- Smith, Keevin M., Alabama Department of Environmental Management, Site
  Assessment Unit, Conversations with and information provided by Mr. John Collins.,
  March 21, 2000.
- 10. Smith, Keevin M., Alabama Department of Environmental Management, Site Assessment Unit, Observations made during site visit., March 21, 2000.
- 11. Department of Conservation and Natural Resources, 1997 Federally Listed Endangered/Threatened Species.
- 12. Alabama State Data Center, Center for Business and Economic Research, College of Commerce and Business Administration, The University of Alabama. 1990 CENSUS Alabama Counties and Cities By Race.

#### REFERENCES CONTIUED

- 13. Teem, David H., et al., Alabama Agricultural Experiment Station, 1986, Vertebrate Animals of Alabama in Need of Special Attention.
- 14. Alabama Department of Environmental Management, Federal Reporting Data System (FRDS-II), Public Water Supply Summary.
- 15. Gibson, Joseph L., Hydrogeologist; <u>Preliminary Assessment of Groundwater on Pollock Collins Site.</u>

Attachment 1 7.5 Minute Topographic Map for Site

Attachment 2 County Map

Attachment 3 Site Diagram

Attachment 4 Flood Map of Pollock Collins Oil Site

Attachment 5 Photos

Attachment 6 Lab Analysis

Attachment 7 Platt map of Pollock Collins Oil

# OVERSIZED DOCUMENT

# OVERSIZED DOCUMENT

#### GENERAL INFORMATION (continued)

Sita Sketch (Show all p	: ertinent features, indicate sources and closest targets, indicate north)
1	Garage Doldanto batteries drum  woody vegetation  old drum  Build- ing
. (	Storage
ا	Office -  Area of House  Oiked Stilled Tanks O Soil
Addie Avenue	
Glenn Ab	Old fuel Funps 4
	Building Building
	Old Fuel pumps woody vegetation


# OVERSIZED DOCUMENT

## **PHOTOGRAPHS**

- 1. The office and storage complex of Pollock Collins Oil; the east side of the site
- 2. Garage
- 3. Old drums, woody vegetation and general debris
- 4. Old truck and auto batteries, old drums
- 5. Pump House
- 6. Storage building littered with old sign and old drums
- 7. Storage building
- 8. Storage building
- 9. Storage building; littered with drums and old gas pumps
- 10. Old gas pumps
- 11. Stilted tanks that are diked
- 12. Pump with area of stained soil
- 13. Pump with area of stained soil

### **POOR LEGIBILITY**

## PORTIONS OF THIS DOCUMENT MAY BE UNREADABLE, DUE TO THE QUALITY OF THE ORIGINAL






























oll Screening Levels: Ingestion (May 1996) (ppm)					NA		NA		NA I		NA	
oil Screening Levels: 1 DAF (May 1996) (ppm)					NA		NA		NA		NA.	
uperfund Chemical Data Matrix: Benchmarks (June 1996) (ppm)					390		NA		NA NA		NA	
isk Based Concentration (RBC) (10/1/98) (ppm)					390		NA		47,000		NA	
Sample Location	XLNo	Cort	Seec	Date/Time	Mo	± Prec	Zr	± Prec	Sr	± Prec	Rb	± Prec
PB-009-01	417		26.7	5/17/00 12:08	<l00< td=""><td>18.6</td><td>335.2</td><td>29.7</td><td>&lt;1.00</td><td>14.85</td><td><l00< td=""><td>0.15</td></l00<></td></l00<>	18.6	335.2	29.7	<1.00	14.85	<l00< td=""><td>0.15</td></l00<>	0.15
PB-009-02	418		22.1	5/17/00 12 09	<l00< td=""><td>22.65</td><td>228.2</td><td>31.5</td><td><l00< td=""><td>19.2</td><td>0.3</td><td>02</td></l00<></td></l00<>	22.65	228.2	31.5	<l00< td=""><td>19.2</td><td>0.3</td><td>02</td></l00<>	19.2	0.3	02
PB-009-03	419		22.3	5/17/00 12:10	<lod< td=""><td>21</td><td>260.8</td><td>31.6</td><td><l00< td=""><td>18.3</td><td>0.3</td><td>0.2</td></l00<></td></lod<>	21	260.8	31.6	<l00< td=""><td>18.3</td><td>0.3</td><td>0.2</td></l00<>	18.3	0.3	0.2
PB-009-04	420		24.3	5/17/00 12:10	<100	18	311.6	29	<1.00	14.4	03	0.2
P8-009-05	421		22.1	5/17/00 12:11	<l00< td=""><td>16.2</td><td>174 4</td><td>23.4</td><td><l00< td=""><td>13.95</td><td><l00< td=""><td>0.3</td></l00<></td></l00<></td></l00<>	16.2	174 4	23.4	<l00< td=""><td>13.95</td><td><l00< td=""><td>0.3</td></l00<></td></l00<>	13.95	<l00< td=""><td>0.3</td></l00<>	0.3
P8-009-06	422		24.3	5/17/00 12:13	<l00< td=""><td>18.45</td><td>375</td><td>31.1</td><td><l00< td=""><td>15</td><td>0.3</td><td>0.2</td></l00<></td></l00<>	18.45	375	31.1	<l00< td=""><td>15</td><td>0.3</td><td>0.2</td></l00<>	15	0.3	0.2
PB-009-07	423		24.4	5/17/00 12:14	<100	19.35	373	32.1	<lod< td=""><td>15.6</td><td>0.3</td><td>0.2</td></lod<>	15.6	0.3	0.2
PB-009-08	424		22.5	5/17/00 12:15	<l00< td=""><td>23.7</td><td>431.2</td><td>41.1</td><td><l00< td=""><td>18.6</td><td>0.6</td><td>0.3</td></l00<></td></l00<>	23.7	431.2	41.1	<l00< td=""><td>18.6</td><td>0.6</td><td>0.3</td></l00<>	18.6	0.6	0.3
PB-009-09	425		22.3	5/17/00 12:15	<lod< td=""><td>21</td><td>351</td><td>34.3</td><td><l00< td=""><td>17.25</td><td>0.3</td><td>02</td></l00<></td></lod<>	21	351	34.3	<l00< td=""><td>17.25</td><td>0.3</td><td>02</td></l00<>	17.25	0.3	02
PB-009-10	426		20.2	5/17/00 12:16	<l00< td=""><td>25.35</td><td>406.8</td><td>41.1</td><td><l00< td=""><td>19.35</td><td><l00< td=""><td>0.3</td></l00<></td></l00<></td></l00<>	25.35	406.8	41.1	<l00< td=""><td>19.35</td><td><l00< td=""><td>0.3</td></l00<></td></l00<>	19.35	<l00< td=""><td>0.3</td></l00<>	0.3
P8-009-60 (0-4')	8		20.2	5/2/00 10:18	<100	24.6	511.6	44	<l00< td=""><td>18</td><td>0.4</td><td>0.2</td></l00<>	18	0.4	0.2
PB-009-60A (0-4")	150		24.2	3/29/00 13:46	<lod< td=""><td>23.4</td><td>518.4</td><td>40.7</td><td>&lt;1.00</td><td>16.65</td><td><l00< td=""><td>0.3</td></l00<></td></lod<>	23.4	518.4	40.7	<1.00	16.65	<l00< td=""><td>0.3</td></l00<>	0.3
P8-009-608 (4-8')	151		22.1	3/29/00 13:51	<l00< td=""><td>18.45</td><td>99.4</td><td>21.9</td><td><l00< td=""><td>15.6</td><td><l00< td=""><td>03</td></l00<></td></l00<></td></l00<>	18.45	99.4	21.9	<l00< td=""><td>15.6</td><td><l00< td=""><td>03</td></l00<></td></l00<>	15.6	<l00< td=""><td>03</td></l00<>	03
P8-009-608 (4-8')	94		20.1	5/2/00 12 31	<l00< td=""><td>19.65</td><td>93.2</td><td>23 1</td><td><l00< td=""><td>15.45</td><td><l00< td=""><td>0.3</td></l00<></td></l00<></td></l00<>	19.65	93.2	23 1	<l00< td=""><td>15.45</td><td><l00< td=""><td>0.3</td></l00<></td></l00<>	15.45	<l00< td=""><td>0.3</td></l00<>	0.3
						755 SEC. 15	200					
No	SAMB_ID2	SAMB ID	SAMA TYPE	SAMB_Descript	CN_Unit	CN_LabValue	PCB Unit	Aroclor 1016	Aroclor 1221	Aroclor 1232	Aroclor 1242	Aroclor 1
38	PB-009	PB-009-04	SOIL		(mg/kg)		(µg/kg)	2,300 UJ	2,300 UJ	2,300 UJ	2,300 UJ	2,300 U
39	PB-009	PB-009-10	SOIL	Pollock-Collins Oil	(mg/kg)		(µg/kg)	22,000 UJ	22,000 UJ	22,000 UJ	22,000 UJ	22,000
40	PB-009	PB-009-60	SOIL	Pollock-Collins Oil (0'-4')			(µg/kg)	200 UJ	200 UJ	200 UJ	200 UJ	200 U.

## CALHOUN CO., ALABAMA

PREPARED UNDER THE DIRECTION
OF THE

## STATE OF ALABAMA

## DEPARTMENT OF REVENUE

AD VALOREM TAX DIVISION


PREPARED BY

## HUNNICUTT & ASSOCIATES, INC. ST. PETERSBURG, FLA.



DATE OF MAP: 10/1/77 DATE OF PHOTOGRAPHY: 1/31/75





#### **LEGEND**

STATE LINE		AREA (FROM DEED)	10.5 Ac.
COUNTY LINE		AREA (CALCULATED)	10.5 Ac. (c)
CORPORATION LINE		DIMENSION (FROM DEE	ED) 16.5
DISTRICT LINE		DIMENSION (SCALED)	66' (s)
ROAD R/W		WATER	
TRAVELED ROAD WAY		INTERSTATE HIGHWAY	<b>3</b>
RAILROAD R/W	<b>==</b>	U.S. HIGHWAY	63
PROPERTY LINE		STATE HIGHWAY	3
LAND HOOK		COUNTY HIGHWAY	17
INTERIOR TRACT LIN	L E, OR	ROADS OR STREETS	BY NAME
ORIGINAL TRACT LIN	E	MAJOR TRANSMISSION LINES	(POWER)
SUBDIVISION LOT N	JMBER 29		2 1
PARCEL NUMBER	15	SECTION CORNERS	11 12
BLOCK LIMIT, (WHERE APPLICABLE	<u>.</u>	STATE PLANE. COORDINATES	NI,085,000
OWNERSHIP MAP BI (WHERE APPLICABLE	оск, <b>2</b>		, in passion
CHURCHES, SCHOOL CEMETERIES, AIRPO GOVERNMENT LAND ETC.	RTS,	ORIGINAL BLOCK NUMBER	5
age assert		ISIONS	
		NGES OR ADDITIONS	
9/90 12 Ms 1-24 5/85 ADS 4-12			
3-24-29 BW 3-04			
1-90-11 al 423.5			
1.692 BW 529	B. pm		


SECTIONS NE 1/4 7

TOWN 16 SOUTH, RANGE 8 EAST

FL.8 EXP 17

11-21-03-07-1

MAP NUMBER



### **Figures**

Figure 1	Pollock Collins Oil, Alabama State map location
Figure 2	Pollock Collins Oil, Anniston, Al., U. S. G. S Topographic Mar 1956 Photorevised 1972
Figure 3	Geologic Map of Alabama, Northeast Sheet 1988

### Figure 1


### Pollock - Collins C.



## Figure 2

#### Site Location Map








Pollock - Collins Oil Anniston, Calhoun County, Alabama

Anniston, Alabama U. S.G.S. Topographic Map 1956 Photo Revised 1972

# Figure 3

#### Geologic Units and Structures Near Pollock – Collins Oil



Ock - Knox Group Undifferentiated

Cc - Conasauga Formation


Cr - Rome Formation

Cs - Shady Dolomite

Cch - Chilhowee Group

tld - Lay Dam Formation

hp - Heffin Phyllite





Geologic Map of Alabama
Northeast Sheet 1988
W.E. Osborne, Michael W. Szabo, Thornton L. Neathery, and Charles W. Copeland Jr.
Geological Survey of Alabama Special Map 220

*				,	SITE:	\$ T-	- 
SEPA Potential Hazardous				GI:	Identification		
Waste					State:	CERCLIS N	( DO W. C. W. C. C.
Prelimi	nary Asse	ssme	nt E	orm	Marc:	covery Date:	2003
1. General Site Informa	tion						
Name: Pollock Collins	0:1	Street Add 605		lenn F	iddie.	Ave.	
City:		State:		<b>Zip Code:</b> 36201	County: Calhoun	Co. Code: A1.015	Cong. Dist:
Latinude: Longin		1 43,50	Acı	<b>e</b>	Status of Site:	□ Not Specifie □ NA (OW pl	od veme, etc.)
2. Owner/Operator Info	rmation						
Owner John Coll.	NS.	Operato	XT.	John	Collin	S	
Street Address: 605 Glenn Add	ic Ave:		Address:	Glenn	Addie	£ Auc	
car Anniston				ston			-
State: Zip Code: Telephone: A1. 36201 (35	b236-6111	State:	<b>Zip C</b> 362		obone: (256) e	236-61	7.1
Type of Ownership:    Frivate							
3. Site Evaluator Inform	ation						
Name of Evaluator: Keevin M. Smith	Agency/Organization	*		Date P	repared:	2000	
Street Address: 1400 Colise	um Blud.		City:	Montgo	swery	State: fix	1
Name of EPA or State Agency Coolect  Keevin M. Smith  1400 College um Blud							
Montgomery			State: Telephone: A1. (334) 279-3076				
4. Site Disposition (for EPA use only)							
Emergency Response/Removal Assessment Recommendation:  Yes No Date:	CERCLIS Recommendati U Higher Priority SI Lower Priority SI NFRAP U RCRA		Signatu Name (		8		

	37 :			
		8		

Potential Hazardous Waste Site Preliminary Assessment Form - Page	of 4 CERCLIS Number: 7/6/				
5. General Site Characteristics					
Predominant Land Uses Within 1 Mile of Site (check all that apply):    Industrial	Setting:  GUrban GSuburban Rural  Paral of Operation: Beginning Year 1938  Ending Year Unknown				
Type of Site Operations (check all that apply):    Manufacturing (must check subcategory)					
☐ Coal ☐ "Nos- or L☐ Oil and Oas ☐ Not Specified☐ Nos-esetaBic Minerals ☐ Other	School, or Workplace:				
6. Waste Characteristics Information					
Source Type: (check all that apply)    Landfill	General Types of Waste (check all that apply)   No				

SEPA Potential Prelimina	CERCLIS Number: 7/6/		
7. Ground Water Par	thway		
Is Oround Water Used for Drinking Water Wathin 4 Miles: D Tes	is There a Suspected Release to Gro Water:  Yes  No	Withdrawa From: 0 - V. Mile	Alation Served by Oround Water
Type of Drinking Water Wells Within 4 Miles (check all that apply):	Have Primary Target Drinking Water Wells Born Identified:	> 1 - 1 Mile > 1 - 2 Miles	0 4/0 400
Depth to Shallowest Aquifer:  25 Post  Karst Terrain/Aquifer Present:  12 Yes    No	Nearest Designated Wellhead Protect Area:  Underlies Site  >0 - 4 Miles  None Within 4 Miles		Miles <u>8/0</u>
8. Surface Water Pa	thway		
Type of Surface Water Draining Site a that apply):    Stream		Shortest Overland Distance From A	any Source to Surface Water:
is There a Suspected Release to Surfac Yes 12-140	e Water:	Site is Located in:  ☐ Angual - 10 yr Floc ☐ > 10 yr - 100 yr Flo ☐ > 100 yr - 500 yr F	codplain loodplain
Drinking Water Intakes Located Along  U-146	the Surface Water Migration Path:	List All Secondary Target Drinking Name Water Body	Water Intakes: Flow (cfs) Population Served
Have Primary Target Drinking Water  Yes.  12-10	latakes Boos Identified:		
If Yes, Easer Population Served by Pri	mary Target Intakes: People	Total within	15 Miles None
Fisheries Located Along the Surface W BYes No No Have Primary Target Fisheries Been Id Yes D-No		List All Socondary Target Fisherics Water Body/Fishery Name Snow Creek Chaccolocco Cr	10 cfs

	*	

Preliminary Assessment		4	CERCLIS Number:				
8. Surface Water Pathway (con	tinued)						
Wetlands Located Along the Surface Water Migration Path:  Other Sensitive Environmenta Located Along the Surface Water Migration Path:  Yes  Other Sensitive Environmenta Located Along the Surface Water Migration Path:							
Have Primary Target Wetlands Boos Identified: ☐ Yes ☑ No	Have Primary Ta	get Sensitive Environments B 9	oca Montified:				
List Socondary Target Wetlands:  Water Body  Flow (cfs) Prontage M	List Secondary To Water Body No h e		Scanitive Environment Type				
9. Soil Exposure Pathway		/					
Are People Occupying Residences or  Attending School or Daycare on or Within 200 Peet of Areas of Known or Suspected  Contamination:  Number of Workers Onsite:  Or Within 200 Feet of Areas of Known or Suspected  Contamination:  Yes							
If Yes, Enter Total Resident Population:  39 People		If You, List Each Terrestrie	al Sensitive Pavironment:				
10. Air Pathway							
Is There a Suspected Release to Air:	Wetlands Located W	ithin 4 Miles of the Site:					
□ No  Eater Total Population on or Within:	□ Yes Ø4%						
Onside 3	2						
0 - 16 Mile Other Sensitive Environments Located Within 4 Miles of the Site:							
> W - W Mile							
> 4 - 1 Mile 4268							
>1 - 2 Miles 1/905 >2 - 3 Miles 1/382	List All Sensitive Environments Within 14 Mile of the Site; Distance Sensitive Environment Type/Wetlands Area (acres)						
>3 · 4 Miles	Onsite	None					
Total Within 4 Miles 39093	0 - W Mile	*					
	> 14 · 14 Mile						